

March 4, 2022

Project/File: 113733881

Todd Olson, Infrastructure Development Coordinator

Municipality of Red Lake
2 Fifth Street, P.O. Box 1000
Balmertown, ON P0V 1C0

Dear Todd Olson, Infrastructure Development Coordinator,

**Reference: Howey Bay Road Bridge and Forestry Road Culvert - OSIM Bridge Inspections 2021
Summary Letter**

As requested by the Municipality of Red Lake Ontario, Stantec Consulting Ltd. (Stantec) completed a visual inspection of the Howey Bay Road Bridge and the Forestry Road Culvert. On December 14 & 15, 2021. Angela Kasdorf, C.E.T. and Vince Friesen, Tech. of Stantec conducted the detailed visual inspections in accordance with the Ontario Structure Inspection Manual (OSIM) standards.

The notes and recommendations of the in-depth inspection are included in the attached inspection reports. The reports include a condition inspection for each accessible element, photographs of key members, and a summary of recommended improvements, including level of priority and estimated repair cost.

Based on the observations made during the inspections, a number of maintenance items are recommended to improve the level of safety of the structures and maintain their current structural capacity and functionality. The maintenance items are accompanied by a recommended timing which can be used to develop maintenance and repair programs. Note that the costs associated with each maintenance item is an opinion of probable cost and should be considered a Preliminary Estimate – Class C. Cost estimates of this level are considered to have an accuracy of +35% to -20% and do not include factors such as risk to the contractor, future market conditions, or contractor capacity.

The intent of this letter is to provide a general summary of the key recommendations and observations.

Howey Bay Road Bridge

1. Replace the missing approach post blocking on the SW side. (<1 year)
2. Repair missing asphalt on the SE approach encroaching the travel lanes (<1 year)
3. Repair approach roadway embankment at the SE corner of the bridge due to the loss of material that is encroaching the roadway and becoming a hazard for vehicles. (<1 year)
4. Replace a section of flexbeam railing on the north side between deck post 3 and northwest approach post 1. (<1 year)
5. Repair the gabion baskets along SU1 and SU2. (<1 year)
6. The deck soffit at SU1 between G1/G2 appears to be temporarily repaired with foam to support the wearing surface. Recommend removing temporary repair and replacing with structural concrete (<1 year)

Reference: Howey Bay Road Bridge and Forestry Road Culvert - OSIM Bridge Inspections 2021 Summary Letter

The Howey Bay Road Bridge continues to deteriorate as observed during this most recent inspection and as summarized below:

- The steel girders have areas of severe corrosion with section loss. The bottom flanges beside the bearings have up to 4mm remaining thickness at SU1 and 9mm at SU2. Approximate original thickness is 12mm measured nearer midspan where there is only light corrosion.
- Rotation of the abutments is causing gaps at the missing deck joint locations and causing spalls in the ballast walls from the girder bottom flanges. Comparing deck measurements, it appears the substructure has moved slightly since the previous inspection in 2019 and we recommend this monitoring continues during future inspections.
- The reasoning for the current 5 tonne load limit posting is unknown.

Based on the condition of the girders and the movement of the abutment Stantec recommends replacing the bridge with a new structure in approximately 1-5 years with a lifespan of 75 years. An example of a new structure would be a new 12.0m long by 7.2m wide concrete channel girder bridge with an estimated cost of \$734,400.

The maintenance items listed above should maintain the bridge's functionality until the bridge is replaced. Maintenance items, rehabilitation, and replacement timing to be reassessed during the next OSIM inspection.

Forestry Road Culvert

1. Rehabilitate the concrete footing that currently has extensive erosion and exposed rebar under the waterline (1-5 years)

Due to limited access, an underwater investigation of the concrete footing was completed in 2017. It is recommended that another underwater investigation be completed to monitor the extent and rate of concrete footing deterioration until the repair is completed. Underwater investigation should compare and contrast to the investigation completed in 2017.

The attached inspection reports further detail the inspection findings.

Stantec was pleased to assist the Municipality of Red Lake with these inspections. If you have any questions regarding the reports, please feel free to contact the undersigned.

Regards,

Eric Tranquada B.Env.D., P.Eng.
Bridge Engineer
Phone: (204) 478-8986
Mobile: (204) 228-2574
Eric.Tranquada@stantec.com

Attachment: Howey Bay Bridge Inspection Report
Forestry Road Culvert Inspection Report

Structure Inspection Manual - Inspection Form

Site Number: Bridge

Inventory Data:

Structure Name	Howey Bay Road Bridge			Water Shed	N/A
Main Hwy/Road #	N/A	On <input checked="" type="checkbox"/> Under <input type="checkbox"/>	Crossing Type:	Navig. Water <input type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/> Road <input checked="" type="checkbox"/> Ped. <input type="checkbox"/> Other <input type="checkbox"/>	
Hwy/Road Name	Howey Bay Road				
Structure Location	N/A				
Latitude	N 51° 01' 14"	Longitude	W 93° 48' 47"		
Owner(s)	Municipality of Red Lake	Heritage Destination:	Not Cons. <input type="checkbox"/> Cons./not App. <input type="checkbox"/> List/not Desig. <input type="checkbox"/> Desig./not List <input type="checkbox"/> Desig. & List <input type="checkbox"/>		
MTO Region	Northwestern	Road Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input type="checkbox"/> Local <input type="checkbox"/>		
Municipality	Red Lake	Posted Speed	40	No. of Lanes	2
MTO District	Kenora	AADT	N/A	% Trucks	N/A
Legal Description	N/A	Inspection Route Sequence	N/A		
Structure Type	Steel Girder	Interchange Number	N/A		
Total Deck Length	6.40 (m)	Interchange Structure Number	N/A		
Overall Str. Width	8.50 (m)	Min. Vertical Clearance	N/A (m)		
Total Deck Area	48.64 (sq.m)	Special Routes:	Transit <input type="checkbox"/> Truck <input type="checkbox"/> School <input type="checkbox"/> Bicycle <input type="checkbox"/>		
Roadway Width	7.40 (m)	Detour Length	N/A (km)		
Skew Angle	0 (Degrees)	Direction of Structure	E - W		
No. of Spans	1	Fill on Structure	N/A (m)		
Span Lengths	5.90 (m)				

Historical Data:

Year Built	Unknown	Last Evaluation	None
Last OSIM Inspection	2019	Current Load Limit	5 (tonnes)
Last Enhanced OSIM Inspection	Unknown	Load Limit By-Law #	
Last Condition Survey	None	By-Law Expiry Date	
Last Underwater Inspection	None		

Rehab History:

Year	Description of Work
2016	Replaced Gabion baskets on embankments with riprap

Scheduled Improvements:					
Recommended Maintenance	Priority	Unit	Estimated Quantity	Avg. Unit Cost	Estimated Cost
Approach Wearing Surface - Asphalt Repair	<1 Year	m ²	1	\$ 300	\$ 300
Embankment - Repair	<1 Year	LS	1	\$ 10,000	\$ 10,000
Gabion Basket - Repair	<1 Year	LS	1	\$ 1,500	\$ 1,500
Barriers - Approach Post blocking - Replace	<1 Year	Each	1	\$ 250	\$ 250
Barriers - Railing System - Replace	<1 Year	m	4	\$ 650	\$ 2,600
Deck Soffit - Concrete Repair	<1 Year	m ²	2.0	\$ 5,000	\$ 10,000
Replace PPCC Girder Bridge	1-5 Years	m ²	86.4	\$ 8,500	\$ 734,400
				Subtotal	\$ 759,050
				Regional Factor	1.5
				Total Estimated Cost	\$ 1,138,600

Appraisal Indices:		Comments
Fatigue		
Seismic		
Scour		
Flood		
Geometrics		
Barrier		
Curb		
Load Capacity		

Field Inspection Information:	
Date of Inspection:	December 14, 2021
Inspector:	Angela Kasdorf, C.E.T., Stantec Consulting Ltd.
Others in Party:	Vince Friesen, Tech., Stantec Consulting Ltd.
Equipment Used:	Standard
Weather:	Clear
Temperature:	-1°C

Additional Investigations Required:	Priority		
	None	Normal	Urgent
Detailed Deck Condition Survey:	X		
Non-destructive Delamination Survey of Asphalt-Covered Deck:	X		
Concrete Substructure Condition Survey:	X		
Detailed Coating Condition Survey:	X		
Detailed Timber Investigation:	X		
Post-Tensioned Strand Investigation:	X		
Underwater Investigation:	X		
Fatigue Investigation:	X		
Seismic Investigation:	X		
Structure Evaluation:	X		
Monitoring of Deformations, Settlements and Movements:		X	
Monitor Crack Widths:	X		
<p>Special Notes: Recommend monitoring movement at SU1 and SU2 abutments by continuing to take gap measurements (refer to photos for gap measurement location). Municipality should give consideration to funding a bridge replacement in 1 to 5 years due to low load posting, abutment movements, steel girder deterioration and lack of proper deck joint assemblies. Bridge replacement recommendation and timing to be reassessed during next inspection.</p> <p>Recommend conducting next OSIM inspection during summer months when the wearing surface and embankments are not covered by snow / ice.</p>			
Next Detailed Visual Inspection:		2023	

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 00 None | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 01 Load carrying capacity | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 02 Excessive deformations (deflections & rotations) | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 03 Continuing settlement | 09 Rough riding surface | 15 Unstable embankments |
| 04 Continuing movements | 10 Surface ponding | 16 Other |
| 05 Seized bearings | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| 05 Bridge Deck Joint Repair | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Data

Element Group:	Approaches	Length:	7.00				
Element Name:	Wearing Surfaces	Width:	7.40				
Location:		Height:	0.10				
Material:	Asphalt	Count	2				
Element Type:		Total Quantity:	103.60				
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>	Limited Inspection	<input checked="" type="checkbox"/> Snow / Ice				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*	08	12
Comments: Light ravelling typical. East approach on South side has embankment loss with missing asphalt (0.6x0.9) encroaching the travel lane.							
Recommended Work: None <input type="checkbox"/> 6-10 Years <input type="checkbox"/> 1-5 Years <input type="checkbox"/> <1 Year <input checked="" type="checkbox"/> Urgent <input type="checkbox"/> Repair asphalt on SE corner in conjunction with SE embankment repair.							

Element Group:	Abutments	Length:	n/a				
Element Name:	Abutment Walls	Width:	9.20				
Location:		Height:	1.07				
Material:	Cast-in-Place Concrete	Count	2				
Element Type:	Reinforced Concrete	Total Quantity:	19.69				
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input checked="" type="checkbox"/> Covered by Debris				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*	00	00
Comments: Light scaling typical. SU1: Delamination with rust staining and efflorescence; mechanical spall under G1. SU2: Delamination with efflorescence; Disintegration on bearing seat between G1-G2. Concrete footing has typical light scaling.							
Recommended Work: None <input checked="" type="checkbox"/> 6-10 Years <input type="checkbox"/> 1-5 Years <input type="checkbox"/> <1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:	Abutments	Length:	n/a				
Element Name:	Ballast Walls	Width:	9.20				
Location:		Height:	0.61				
Material:	Cast-in-Place Concrete	Count	2				
Element Type:	Reinforced Concrete	Total Quantity:	11.22				
Environment:	Benign <input type="checkbox"/> Moderate <input checked="" type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input type="checkbox"/>				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*	00	00
Comments: Light scaling typical. Isolated hairline cracks and pop-outs. SU1: Mechanical spall behind both G1 and G6 bottom flange.							
Recommended Work: None <input checked="" type="checkbox"/> 6-10 Years <input type="checkbox"/> 1-5 Years <input type="checkbox"/> <1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

Element Data

Element Group:	Abutments	Length:	n/a				
Element Name:	Bearings	Width:	n/a				
Location:	G1 / G6	Height:	n/a				
Material:	Neoprene	Count	4				
Element Type:	Elastomeric Pad	Total Quantity:	4				
Environment:	Benign <input type="checkbox"/> Moderate <input checked="" type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input type="checkbox"/>				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	Each	0	4	0	0	00	00

Comments:
Light bulging typical. Girder bottom flanges are very close to touching the abutment seat and SU1 G1 has caused a mechanical spall on the abutment concrete under the girder.

Recommended Work: None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

Element Group:	Abutments	Length:	n/a				
Element Name:	Bearings	Width:	n/a				
Location:	G2 / G3 / G4 / G5	Height:	n/a				
Material:	Steel & Neoprene	Count	8				
Element Type:	Plate & Pad	Total Quantity:	8				
Environment:	Benign <input type="checkbox"/> Moderate <input checked="" type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input type="checkbox"/>				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	Each	0	0	8	0	00	00

Comments:
Bearings have typical medium corrosion on steel plate and medium bulging of the neoprene pad.

Recommended Work: None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

Element Group:	Accessories	Length:	n/a				
Element Name:	Signs	Width:	n/a				
Location:		Height:	n/a				
Material:		Count	5				
Element Type:	Hazard Signs & Load Limit Sign	Total Quantity:	5				
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>	Limited Inspection	<input type="checkbox"/>				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	Each	5	0	0	0	00	00

Comments:
4 hazard markers located at bridge corners. 1 load limit sign located NE of structure. No observed defects.
A load limit sign is missing on the SW side of the structure, however the bridge is the only means of access to this side of the peninsula.

Recommended Work: None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

Element Data

Element Group:	Beams / MLE's	Length:	6.40				
Element Name:	Girders	Width:	0.18				
Location:		Height:	0.41				
Material:	Steel	Count	6				
Element Type:	I Type	Total Quantity:	52.22				
Environment:	Benign <input type="checkbox"/> Moderate <input checked="" type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection <input type="checkbox"/>				
Protection System:							
Condition	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	Maint. Needs
Data:	m ²	0.00	41.16	3.61	7.45	01	00

Comments:
 Light corrosion typical. Medium corrosion at the ends throughout. SU1: Isolated area of severe corrosion on the web. Typical severe corrosion and section loss on bottom flanges up to 8mm at SU1 and 3mm at SU2. (Flange thickness should be ~12mm)

Recommended Work: None ☐ 6-10 Years ☐ 1-5 Years ☒ <1 Year ☐ Urgent ☐
 Recommend replacing bridge.

Element Group:	Beams / MLE's	Length:	1.50				
Element Name:	Diaphragms	Width:	0.05				
Location:		Height:	0.05				
Material:	Steel	Count	10				
Element Type:	Pipe	Total Quantity:	10				
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection <input type="checkbox"/>				
Protection System:	Galvanizing						
Condition	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	Maint. Needs
Data:	Each	10	0	0	0	00	00

Comments:
 No observed defects.

Recommended Work: None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

Element Group:	Barriers	Length:	20.20				
Element Name:	Railing Systems	Width:	n/a				
Location:		Height:	0.90				
Material:	Steel	Count	2				
Element Type:	Flex Beam	Total Quantity:	40.40				
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>		Limited Inspection <input type="checkbox"/>				
Protection System:	Galvanizing						
Condition	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	Maint. Needs
Data:	m	31.80	0.80	0.00	7.80	01	03

Comments:
 Isolated light corrosion. Isolated permanent deformations. No other observed defects.

Recommended Work: None ☐ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☒ Urgent ☐
 Replace section of north railing from deck Post 3 to west approach Post 1.

* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

Structure Inspection Manual - Inspection Form

Site Number: **Bridge**

Element Data

Element Group:	Barriers		Length:	0.15			
Element Name:	Posts		Width:	0.20			
Location:	Deck Top		Height:	1.60			
Material:	Steel		Count	8			
Element Type:	Wide Flange		Total Quantity:	8			
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>		Limited Inspection	<input type="checkbox"/>			
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	Each	0	8	0	0	00	00

Comments:
Light corrosion typical.

Recommended Work: None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

Element Group:	Barriers		Length:	0.20			
Element Name:	Posts		Width:	0.20			
Location:	Approaches		Height:	1.10			
Material:	Wood		Count	12			
Element Type:	Rectangular Solid		Total Quantity:	12			
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>		Limited Inspection	<input type="checkbox"/>			
Protection System:	Green Treated					Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	Each	0	0	4	8	01	09

Comments:
Light weathering typical. Medium to severe checks/splits. SW: Post 3, rotated blocking; Post 4, missing blocking. NE: Post 1, non-standard sizing (0.1m L x 0.1m W). Bottoms of Post 1 at SW, SE, and NW are moving out due to loss of supporting embankment material.

Recommended Work: None ☐ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☒ Urgent ☐
Replace SW Post 4 blocking.

Element Group:			Length:				
Element Name:			Width:				
Location:			Height:				
Material:			Count				
Element Type:			Total Quantity:				
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection	<input type="checkbox"/>			
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:							

Comments:

Recommended Work: None ☐ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

Structure Inspection Manual - Inspection Form

Site Number:

Bridge

Element Data

Element Group:	Coatings		Length:	n/a			
Element Name:	Railing Systems		Width:	n/a			
Location:			Height:	n/a			
Material:	Galvanizing		Count	n/a			
Element Type:	Hot Dip Galvanizing		Total Quantity:	40.40			
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>		Limited Inspection <input type="checkbox"/>				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	m	39.60	0.80	0.00	0.00	00	00
Comments: Isolated category 2 rusting. No other observed defects.							
Recommended Work: None <input checked="" type="checkbox"/> 6-10 Years <input type="checkbox"/> 1-5 Years <input type="checkbox"/> <1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:	Coatings		Length:	n/a			
Element Name:	Diaphragms		Width:	n/a			
Location:			Height:	n/a			
Material:	Galvanizing		Count	n/a			
Element Type:	Hot Dip Galvanizing		Total Quantity:	10			
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection <input type="checkbox"/>				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	Each	10	0	0	0	00	00
Comments: No observed defects.							
Recommended Work: None <input checked="" type="checkbox"/> 6-10 Years <input type="checkbox"/> 1-5 Years <input type="checkbox"/> <1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:			Length:				
Element Name:			Width:				
Location:			Height:				
Material:			Count				
Element Type:			Total Quantity:				
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection <input type="checkbox"/>				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:							
Comments:							
Recommended Work: None <input type="checkbox"/> 6-10 Years <input type="checkbox"/> 1-5 Years <input type="checkbox"/> <1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

Element Data

Element Group:	Decks		Length:	6.40			
Element Name:	Wearing Surface		Width:	7.40			
Location:			Height:	0.10			
Material:	Asphalt		Count	n/a			
Element Type:			Total Quantity:	47.36			
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>		Limited Inspection	<input checked="" type="checkbox"/> Snow / Ice			
Protection System:						Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²	0.00	47.36	0.00	0.00	00	00

Comments:
Light ravelling typical on exposed areas.

Recommended Work: None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

Element Group:	Decks		Length:	6.40			
Element Name:	Deck Top		Width:	7.60			
Location:			Height:	0.36			
Material:	Cast-in-Place Concrete		Count	n/a			
Element Type:			Total Quantity:	48.64			
Environment:	Benign <input type="checkbox"/> Moderate <input checked="" type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection	<input checked="" type="checkbox"/> Snow / Ice			
Protection System:						Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²	0.00	48.64	0.00	0.00	00	00

Comments:
Exposed deck top has light scaling typical.

Recommended Work: None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

Element Group:	Decks		Length:	6.40			
Element Name:	Soffit		Width:	n/a			
Location:	Exterior		Height:	0.36			
Material:	Cast-in-Place Concrete		Count	2			
Element Type:			Total Quantity:	4.61			
Environment:	Benign <input type="checkbox"/> Moderate <input checked="" type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection	<input type="checkbox"/>			
Protection System:						Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²	0.00	4.21	0.30	0.10	00	00

Comments:
Light scaling typical. Medium scaling on north side. Delamination at post location on SE side.

Recommended Work: None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

Element Data

Element Group:	Decks	Length:	6.40				
Element Name:	Soffit	Width:	7.60				
Location:	Interior	Height:	n/a				
Material:	Cast-in-Place Concrete	Count	n/a				
Element Type:		Total Quantity:	48.64				
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input type="checkbox"/>				
Protection System:							
Condition	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	Maint. Needs
Data:	m ²	0.00	38.47	0.27	9.90	01	08

Comments:
 Light scaling typical. Light to severe honeycombing. Rust staining at the abutments. Typical delaminations and spalls with exposed corroded reinforcement at the abutments. Full depth section loss at SU1 between G1/G2 (~0.6x0.2) temporarily repaired with foam to support wearing surface.

Recommended Work: None ☐ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☒ Urgent ☐
 Repair spall at SU1 between G1/G2 with structural concrete.

Element Group:		Length:					
Element Name:		Width:					
Location:		Height:					
Material:		Count					
Element Type:		Total Quantity:					
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input type="checkbox"/>				
Protection System:							
Condition	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	Maint. Needs
Data:							

Comments:

Recommended Work: None ☐ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

Element Group:		Length:					
Element Name:		Width:					
Location:		Height:					
Material:		Count					
Element Type:		Total Quantity:					
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input type="checkbox"/>				
Protection System:							
Condition	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	Maint. Needs
Data:							

Comments:

Recommended Work: None ☐ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

Element Data

Element Group:	Embankments & Streams	Length:	n/a			
Element Name:	Streams & Waterways	Width:	n/a			
Location:		Height:	n/a			
Material:		Count	n/a			
Element Type:	Straight	Total Quantity:	All			
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input checked="" type="checkbox"/> Ice			
Protection System:				Perform. Deficiencies		Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*	
Data:	All		All			00 00

Comments:
Depth of water is 0.10m. Clearance is 2.40m. Stream flows from south to north. Slight scour at upstream of structure.

Recommended Work: None☒ 6-10 Years☐ 1-5 Years☐ <1 Year☐ Urgent☐

Element Group:	Embankments & Streams	Length:	n/a			
Element Name:	Slope Protection	Width:	n/a			
Location:		Height:	n/a			
Material:	Field Rock / Gabions	Count	n/a			
Element Type:	Rock Protection	Total Quantity:	All			
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input checked="" type="checkbox"/> Snow			
Protection System:				Perform. Deficiencies		Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*	
Data:	All			All		15 18

Comments:
Limited inspection due to snow on the embankments, exposed areas of the embankments appear to have no observed defects. Gabion baskets in front of abutments have areas of light to severe corrosion with some section loss of the wire especially along the bottom of SU1 and SU2. No significant movement observed.

Recommended Work: None☐ 6-10 Years☐ 1-5 Years☐ <1 Year☒ Urgent☐
Repair wire on gabion baskets at the bottom of SU1 and SU2.

Element Group:	Embankments & Streams	Length:	n/a			
Element Name:	Embankments	Width:	n/a			
Location:		Height:	n/a			
Material:	Vegetation	Count	n/a			
Element Type:		Total Quantity:	All			
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input checked="" type="checkbox"/> Snow			
Protection System:				Perform. Deficiencies		Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*	
Data:	All				All	08,15 13

Comments:
Limited inspection due to snow, assume concrete footing is still undermining on the SE corner by 0.40 m as noted in previous inspection.
Loss of roadway material encroaching the roadway with severe loss at SE. Supporting material loss around barrier approach posts.

Recommended Work: None☐ 6-10 Years☐ 1-5 Years☐ <1 Year☒ Urgent☐
Repair loss of material at SE corner at approaches.

* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

Site Number: Bridge

Element Group:	Foundations		Length:			n/a	
Element Name:	Foundation		Width:			n/a	
Location:	Abutment @ SU1 and SU2		Height:			n/a	
Material:			Count			n/a	
Element Type:			Total Quantity:			n/a	
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection <input type="checkbox"/>				
Protection System:						Perform.	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*	Deficiencies	
Data:						04	
Comments:							
Bottom of SU1 and SU2 abutments are rotating in towards the stream. Gaps between top of ballast wall and end of deck top at SU1 are: NE @ 32mm, SE @ 38mm; at SU2 are: NW @ 20mm, SW @ 9mm. Compared with previous inspection there is very slight movement. Continue to monitor potential movement at next inspection.							
Recommended Work:		None <input type="checkbox"/>	6-10 Years <input type="checkbox"/>	1-5 Years <input type="checkbox"/>	<1 Year <input type="checkbox"/>	Urgent <input type="checkbox"/>	

Element Group:		Length:						
Element Name:		Width:						
Location:		Height:						
Material:		Count						
Element Type:		Total Quantity:						
Environment:		Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection <input type="checkbox"/>				
Protection System:								
Condition Data:	Units		Exc.	Good	Fair	Poor*	Perform. Deficiencies	Maint. Needs
Comments: 								
Recommended Work: None <input type="checkbox"/> 6-10 Years <input type="checkbox"/> 1-5 Years <input type="checkbox"/> <1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>								

Element Group:		Length:				
Element Name:		Width:				
Location:		Height:				
Material:		Count				
Element Type:		Total Quantity:				
Environment:		Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/> Limited Inspection <input type="checkbox"/>				
Protection System:					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor*	
Comments: 						
Recommended Work: None <input type="checkbox"/> 6-10 Years <input type="checkbox"/> 1-5 Years <input type="checkbox"/> <1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>						

2-52

2021 OSIM Visual Inspections
Howey Bay Bridge
2021-12-14



Looking West towards SU1.



Typical Wearing Surface.



Upstream looking South.



Downstream looking North.



South elevation.



North elevation.



NE embankment.



SE embankment.



SW embankment.

2021 OSIM Visual Inspections
Howey Bay Bridge
2021-12-14



NW embankment.



SU1 East abutment



SU2 West abutment.



Typical North railing.



Typical North posts.



Typical interior bearing - SU1.



Typical exterior bearing - SU2.



Typical interior bearing - SU2.



Approaches - Wearing surface - SE.
 Note: Missing asphalt encroaching travel lane.

2021 OSIM Visual Inspections
Howey Bay Bridge
2021-12-14



SU1 Abutment wall. Note: Typical delamination and rust staining.



SU1 Abutment wall. Note: Spall below G1.



SU2 Abutment wall. Note: Typical delamination and rust staining.



SU2 Abutment wall - between G1/G2. Note: Disintegration of bearing seat.



SU1 Ballast wall - SE. Note: Mechanical spall behind G1 bottom flange.



SU1 Ballast wall - NE. Note: Mechanical spall behind G6 bottom flange.



G1 @ SU1. Note: Medium corrosion on web.



G1 @ SU1. Note: Typical corrosion.



G2 @ SU1. Note: Typical corrosion.

2021 OSIM Visual Inspections
Howey Bay Bridge
2021-12-14



G2 @ SU1. Note: Severe section loss on the bottom flange.



G3 @ SU1. Note: Typical corrosion.



G5 @ SU1. Note: Typical corrosion.



G5 @ SU1. Note: Severe section loss on the bottom flange.



G6 @ SU1. Note: Medium to severe corrosion on web.



Railing - North. Note: Permanent deformation.



Approach Railing - SW. Note: Broken blocking at Post 4.



Coatings - Railing. Note: Typical rusting.



Deck Soffit - Exterior - SE side. Note: Spall behind post.

2021 OSIM Visual Inspections
Howey Bay Bridge
2021-12-14



Deck Soffit - Interior - SU1. Note: Typical delamination.



Deck Soffit - Interior - SU1 between G1/G2. Note: Spall and temporary repair.



Deck Soffit - Interior - SU2 between G4/G5. Note: Typical delamination, spall, and exposed rebar.




Slope Protection - SU2. Note: Typical hole in wires.



Foundation - NE. Note: Gap between deck top and ballast wall at SU1.



Foundation - SE. Note: Gap between deck top and ballast wall at SU1.



Foundation - SW. Note: Gap between deck top and ballast wall at SU2.



Foundation - NW. Note: Gap between deck top and ballast wall at SU2.



Typical Sign - NE.

Structure Inspection Manual - Inspection Form

Site Number: Culvert

Inventory Data:

Structure Name	Forestry Road Concrete Box Culvert			Water Shed	N/A		
Main Hwy/Road #	N/A	On <input checked="" type="checkbox"/>	Under <input type="checkbox"/>	Crossing Type:	Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/> Road <input checked="" type="checkbox"/> Ped. <input type="checkbox"/> Other <input type="checkbox"/>	Non-Navig. Water <input type="checkbox"/> Ped. <input type="checkbox"/> Other <input type="checkbox"/>	
Hwy/Road Name	Forestry Road						
Structure Location	Skookum Bay						
Latitude	N 51° 01' 46"		Longitude	W 93° 50' 51"			
Owner(s)	Municipality of Red Lake		Heritage Destination:	Not Cons. <input type="checkbox"/> Cons./not App. <input type="checkbox"/> List/not Desig. <input type="checkbox"/> Desig./not List <input type="checkbox"/> Desig. & List <input type="checkbox"/>			
MTO Region	Northwestern		Road Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input type="checkbox"/> Local <input type="checkbox"/>			
Municipality	Red Lake		Posted Speed	40	No. of Lanes	2	
MTO District	Kenora		AADT	N/A	% Trucks	N/A	
Legal Description	N/A		Inspection Route Sequence	N/A			
Structure Type	Concrete Box Culvert		Interchange Number	N/A			
Total Deck Length	20.10	(m)	Interchange Structure Number	N/A			
Overall Str. Width	5.60	(m)	Min. Vertical Clearance	N/A (m)			
Total Deck Area	N/A	(sq.m)	Special Routes:	Transit <input type="checkbox"/> Truck <input type="checkbox"/> School <input type="checkbox"/> Bicycle <input type="checkbox"/>			
Roadway Width	7.50	(m)	Detour Length	N/A (km)			
Skew Angle	0	(Degrees)	Direction of Structure	N - S			
No. of Spans	1		Fill on Structure	0.30 (m)			
Span Lengths	5.60 (m)						

Historical Data:

Year Built	Unknown	Last Evaluation	None
Last OSIM Inspection	2019	Current Load Limit	Unknown (tonnes)
Last Enhanced OSIM Inspection	Not Req'd	Load Limit By-Law #	
Last Condition Survey	None	By-Law Expiry Date	
Last Underwater Inspection	2017		

Rehab History:

Year	Description of Work
2016	Replaced barrier posts and railing systems
2016	Installed riprap at inlet and outlet
2016	Repaved deck wearing surface

Appraisal Indices:		Comments
Fatigue		
Seismic		
Scour		
Flood		
Geometrics		
Barrier		
Curb		
Load Capacity		

Field Inspection Information:	
Date of Inspection:	December 15, 2021
Inspector:	Angela Kasdorf, C.E.T., Stantec Consulting Ltd.
Others in Party:	Vince Friesen, Tech., Stantec Consulting Ltd.
Equipment Used:	Standard, Boat
Weather:	Sunny
Temperature:	-1°C

Additional Investigations Required:	Priority		
	None	Normal	Urgent
Detailed Deck Condition Survey:	X		
Non-destructive Delamination Survey of Asphalt-Covered Deck:	X		
Substructure Condition Survey:	X		
Detailed Coating Condition Survey:	X		
Underwater Investigation:		X	
Fatigue Investigation:	X		
Structure Evaluation:	X		
Monitoring of Deformations, Settlements and Movements:	X		
Replace Structure:	X		
Rehabilitate Structure:	X		
Hydraulic Evaluation:	X		
Geotechnical Evaluation:	X		
Other:			
<p>Special Notes: Cathodic protection test station marker for buried natural gas pipeline located on SW and NW embankments. Buried natural gas pipeline marker located on NW embankment.</p> <p>Underwater investigation of concrete footing completed in 2017; recommend conducting another underwater investigation to monitor extent and rate of concrete footing deterioration. Underwater investigation should compare and contrast to the investigation completed in 2017.</p> <p>Recommend conducting next OSIM inspection during summer months when the wearing surface and embankments are not covered by snow / ice.</p>			
Next Detailed Visual Inspection:		2023	

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 00 None | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 01 Load carrying capacity | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 02 Excessive deformations (deflections & rotations) | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 03 Continuing settlement | 09 Rough riding surface | 15 Unstable embankments |
| 04 Continuing movements | 10 Surface ponding | 16 Other |
| 05 Seized bearings | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| 05 Bridge Deck Joint Repair | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Structure Inspection Manual - Inspection Form

Site Number: **Culvert**

Element Data

Element Group:	Accessories	Length:	n/a				
Element Name:	Signs	Width:	n/a				
Location:		Height:	n/a				
Material:	Steel / Aluminum	Count	4				
Element Type:	Hazard Markers	Total Quantity:	4				
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>		Limited Inspection <input type="checkbox"/>				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	Each	4	0	0	0	00	00
Comments: No observed defects.							
Recommended Work: None <input checked="" type="checkbox"/> 6-10 Years <input type="checkbox"/> 1-5 Years <input type="checkbox"/> <1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:		Length:					
Element Name:		Width:					
Location:		Height:					
Material:		Count					
Element Type:		Total Quantity:					
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection <input type="checkbox"/>				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:							
Comments:							
Recommended Work: None <input type="checkbox"/> 6-10 Years <input type="checkbox"/> 1-5 Years <input type="checkbox"/> <1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:		Length:					
Element Name:		Width:					
Location:		Height:					
Material:		Count					
Element Type:		Total Quantity:					
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection <input type="checkbox"/>				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:							
Comments:							
Recommended Work: None <input type="checkbox"/> 6-10 Years <input type="checkbox"/> 1-5 Years <input type="checkbox"/> <1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

Element Data

Element Group:	Barriers		Length:	19.00			
Element Name:	Railing Systems		Width:	n/a			
Location:			Height:	0.90			
Material:	Steel		Count	2			
Element Type:	Flex Beam		Total Quantity:	38.00			
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>		Limited Inspection <input checked="" type="checkbox"/>	Snow			
Protection System:	Galvanizing					Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	m	37.80	0.00	0.00	0.20	00	00

Comments:

West: Isolated permanent deformations.

No other observed defects.

Recommended Work:None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

Element Group:	Barriers		Length:	0.20			
Element Name:	Posts		Width:	0.20			
Location:			Height:	1.40			
Material:	Wood		Count	6			
Element Type:	Rectangular Solid		Total Quantity:	6			
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>		Limited Inspection <input checked="" type="checkbox"/>	Snow			
Protection System:	Green Treated					Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	Each	0	0	1	5	00	00

Comments:

Timber posts are located on top of culvert. Light weathering typical. Light to severe checks/splits.

Recommended Work:None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

Element Group:	Barriers		Length:	0.10			
Element Name:	Posts		Width:	0.15			
Location:			Height:	1.40			
Material:	Steel		Count	16			
Element Type:	Wide Flange		Total Quantity:	17.92			
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>		Limited Inspection <input checked="" type="checkbox"/>	Snow			
Protection System:	Galvanizing					Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	m ²	17.92	0.00	0.00	0.00	00	00

Comments:

No observed defects.

Recommended Work:None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

Structure Inspection Manual - Inspection Form

Site Number: **Culvert**

Element Data

Element Group:	Culverts	Length:	20.10				
Element Name:	Barrels	Width:	5.60				
Location:		Height:	2.00				
Material:	Cast-in-Place Concrete	Count	1				
Element Type:	Box with Open Bottom	Total Quantity:	192.96				
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input checked="" type="checkbox"/> Water Depth				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²	0.00	192.60	0.00	0.36	00	00

Comments:
Light scaling typical. Hairline to narrow vertical cracks on walls and transverse cracks on soffit. Isolated active wet area with hairline cracks on the soffit near the inlet (0.6x0.6).

Recommended Work: None☒ 6-10 Years☐ 1-5 Years☐ <1 Year☐ Urgent☐

Element Group:	Culverts	Length:	n/a				
Element Name:	Inlet Components	Width:	n/a				
Location:	West	Height:	n/a				
Material:	Cast-in-Place Concrete	Count	1				
Element Type:	Head Wall	Total Quantity:	3.14				
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input type="checkbox"/>				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²	0.00	2.58	0.00	0.56	00	00

Comments:
Light scaling typical. Concrete erosion along footing at waterline. Disintegration at NW and SW corner of footing.

Recommended Work: None☒ 6-10 Years☐ 1-5 Years☐ <1 Year☐ Urgent☐

Element Group:	Culverts	Length:	n/a				
Element Name:	Outlet Components	Width:	n/a				
Location:	East	Height:	n/a				
Material:	Cast-in-Place Concrete	Count	1				
Element Type:	Head Wall	Total Quantity:	3.14				
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input type="checkbox"/>				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²	0.00	2.74	0.00	0.40	00	00

Comments:
Light scaling typical. Disintegration at NE and SE corner of footing.

Recommended Work: None☒ 6-10 Years☐ 1-5 Years☐ <1 Year☐ Urgent☐

* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

Structure Inspection Manual - Inspection Form

Site Number: **Culvert**

Element Data

Element Group:	Culverts		Length:	20.10			
Element Name:	Footing		Width:	n/a			
Location:			Height:	1.98			
Material:	Cast-in-Place Concrete		Count	2			
Element Type:			Total Quantity:	79.60			
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection	<input checked="" type="checkbox"/> Water			
Protection System:						Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²	0.00	55.48	4.02	20.10	01	08

Comments:

Light scaling typical. Medium to severe scaling and concrete erosion along waterline. Disintegration with exposed reinforcement along length of both footings below waterline up to ~450mm into south wall and up to ~400mm into north wall.

Recommended Work:

None ☐ 6-10 Years ☐ 1-5 Years ☒ <1 Year ☐ Urgent ☐

Rehabilitate concrete footings.

Element Group:			Length:				
Element Name:			Width:				
Location:			Height:				
Material:			Count				
Element Type:			Total Quantity:				
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection	<input type="checkbox"/>			
Protection System:						Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor*		

Comments:

Recommended Work:

None ☐ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

Element Group:			Length:				
Element Name:			Width:				
Location:			Height:				
Material:			Count				
Element Type:			Total Quantity:				
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection	<input type="checkbox"/>			
Protection System:						Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor*		

Comments:

Recommended Work:

None ☐ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

Element Data

Element Group:	Coatings		Length:	n/a			
Element Name:	Railing System		Width:	n/a			
Location:			Height:	n/a			
Material:	Galvanizing		Count	n/a			
Element Type:	Hot Dip Galvanizing		Total Quantity:	38.00			
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>		Limited Inspection	<input checked="" type="checkbox"/> Snow			
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	m	38.00	0.00	0.00	0.00	00	00
Comments: No observed defects.							
Recommended Work: None <input checked="" type="checkbox"/> 6-10 Years <input type="checkbox"/> 1-5 Years <input type="checkbox"/> <1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:	Coatings		Length:	n/a			
Element Name:	Posts		Width:	n/a			
Location:			Height:	n/a			
Material:	Galvanizing		Count	n/a			
Element Type:	Hot Dip Galvanizing		Total Quantity:	17.92			
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>		Limited Inspection	<input checked="" type="checkbox"/> Snow			
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	m ²	17.92	0.00	0.00	0.00	00	00
Comments: No observed defects.							
Recommended Work: None <input checked="" type="checkbox"/> 6-10 Years <input type="checkbox"/> 1-5 Years <input type="checkbox"/> <1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:			Length:				
Element Name:			Width:				
Location:			Height:				
Material:			Count				
Element Type:			Total Quantity:				
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection	<input type="checkbox"/>			
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:							
Comments:							
Recommended Work: None <input type="checkbox"/> 6-10 Years <input type="checkbox"/> 1-5 Years <input type="checkbox"/> <1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

Element Data

Element Group:	Decks		Length:	15.00			
Element Name:	Wearing Surface		Width:	7.50			
Location:			Height:	0.05			
Material:	Asphalt		Count	2			
Element Type:			Total Quantity:	225.00			
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>		Limited Inspection	<input checked="" type="checkbox"/> Snow			
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	m ²	0.00	0.00	225.00	0.00	00	00

Comments:

Limited inspection. Previous reports indicate medium ravelling typical. Light to medium map cracking on approaches. Isolated medium transverse crack above culvert. Asphalt patches present.

Recommended Work:

None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

Element Group:			Length:				
Element Name:			Width:				
Location:			Height:				
Material:			Count				
Element Type:			Total Quantity:				
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection	<input type="checkbox"/>			
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:							

Comments:**Recommended Work:**

None ☐ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

Element Group:			Length:				
Element Name:			Width:				
Location:			Height:				
Material:			Count				
Element Type:			Total Quantity:				
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>		Limited Inspection	<input type="checkbox"/>			
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:							

Comments:**Recommended Work:**

None ☐ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

Structure Inspection Manual - Inspection Form

Site Number: **Culvert**

Element Data

Element Group:	Embankments & Streams	Length:	n/a				
Element Name:	Streams & Waterways	Width:	n/a				
Location:		Height:	n/a				
Material:		Count	n/a				
Element Type:	Straight	Total Quantity:	All				
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input type="checkbox"/>				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	All		All			00	00

Comments:
Clearance is 2.05 m. Depth of water is 1.70 m. Streams flows from west to east. Isolated area of slight scour under the north wall (See 2017 underwater investigation video at 8:08 minutes).

Recommended Work: None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

Element Group:	Embankments & Streams	Length:	n/a				
Element Name:	Slope Protection	Width:	n/a				
Location:		Height:	n/a				
Material:	Field Stone	Count	n/a				
Element Type:	Rock Protection	Total Quantity:	All				
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input checked="" type="checkbox"/> Snow				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	All	All				00	00

Comments:
No observed defects.

Recommended Work: None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

Element Group:	Embankments & Streams	Length:	n/a				
Element Name:	Embankments	Width:	n/a				
Location:		Height:	n/a				
Material:	Vegetation	Count	n/a				
Element Type:		Total Quantity:	All				
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>	Limited Inspection	<input checked="" type="checkbox"/> Snow				
Protection System:						Perform. Deficiencies	Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*		
Data:	All	All				00	00

Comments:
No observed defects.

Recommended Work: None ☒ 6-10 Years ☐ 1-5 Years ☐ <1 Year ☐ Urgent ☐

* A quantity must be estimated using the appropriate unit (e.g. m²). Percentage should not be used.

2021 OSIM Visual Inspections
Forestry Road Culvert
2021-12-15



Looking South towards Barrel.



Upstream looking West.



Downstream looking East



West elevation - Inlet



West elevation - Inlet.



East elevation - Outlet.



East elevation - Outlet



Typical wearing surface.



Looking East into barrel from Inlet.

2021 OSIM Visual Inspections
Forestry Road Culvert
2021-12-15



Looking West into barrel from Outlet.



Typical West railing.



Culvert North Footing. Note:
Disintegration and erosion of concrete footing with exposed rebar.



Culvert North Footing at midspan. Note:
Disintegration (~400mm deep) of footing with exposed rebar.



Culvert North Footing. Note:
Disintegration and erosion of footing with exposed rebar.



Culvert South Footing. Note:
Disintegration and erosion of concrete footing with exposed rebar.



Culvert South Footing. Note:
Disintegration and erosion of concrete footing with exposed rebar.



Culvert South Footing at midspan. Note:
Disintegration (~450mm deep) of footing with exposed rebar.



Culvert South Footing. Note:
Disintegration and erosion of concrete footing with exposed rebar.

2021 OSIM Visual Inspections
Forestry Road Culvert
2021-12-15



Culvert Barrel - South wall. Note typical vertical cracks.



Culvert Soffit near Inlet. Note: Isolated active wet area with hairline cracks.



Inlet - NW corner. Note: Disintegration and erosion of concrete footing with exposed rebar.



Inlet - SW corner. Note: Disintegration of footing



Outlet - NE corner. Note: Disintegration and erosion of concrete footing.



Outlet - SE corner. Note: Disintegration and erosion of concrete footing.



NW embankment. Note: Natural gas pipeline and cathodic protection markers.

To: Todd Olson, Infrastructure Development Coordinator
Municipality of Red Lake
2 Fifth Street, P.O. Box 1000
Balmertown, ON P0V 1C0

From: Eric Tranquada, B.Env.D., P.Eng.
Bridge Engineer

Project/File: 113733881 Date: April 4, 2022

Reference: Howey Bay Bridge and Forestry Road Culvert - OSIM Inspection 2021 - Bridge Condition Index

The Municipality of Red Lake (MU) retained Stantec Consulting Ltd. (Stantec) to undertake the detailed visual structural inspections of the Howey Bay Road Bridge and the Forestry Road Culvert in 2021.

A Bridge Condition Index (BCI) value for each structure was to be calculated as an add-on to that assignment. The BCI for each structure was calculated in accordance with the Ontario Ministry of Transportation Engineering Standards Branch July 30, 2009 manual: *Bridge Condition Index (BCI) – An Overall Measure of Bridge Condition*.

The table below provides BCI ranges that generally give a good indication to the overall condition of the structure; however, it is important to note that a critical defect may still exist even though the bridge may have a relatively high BCI. Defects that may cause a safety concern for the public or a poor condition that could cause a sudden structural failure would not necessarily be accounted for in this BCI calculation.

The BCI manual states, “The BCI is calculated using asset management principals based on the remaining economic worth of the bridge. It is based on the premise that a bridge starts at a new condition and deteriorates to a lower condition with time. It uses actual inspection data from the various bridge elements and as the elements deteriorate, they have a lower economic value. Essentially, the BCI is a weighted average of all elements (since all elements are not of equal value to the bridge) and all Condition States (since each condition state represents a certain degree of loss of value of the element). The BCI begins at 100 when the bridge is in new condition and theoretically becomes 0 as all elements become fully in Poor condition. Practically, it is impossible for the BCI to fall to 0 since the entire bridge does not become poor before rehabilitation work is performed.”

The BCI number range correlates with the overall bridge condition. The ranges are listed in Table 1 below.

Table 1 - BCI Range Description

BCI Number Range	Bridge Condition
100	Excellent (like new)
≥ 70 to <100	Good
≥60 to <70	Fair
<60	Poor

Reference: Howey Bay Bridge and Forestry Road Culvert - OSIM Inspection 2021 - Bridge Condition Index

Table 2 provides a summary of the BCI calculated for each structure. Each individual BCI calculation sheet can be found attached to this memo.

Table 2 - Structure BCI Values

Structure	BCI
Howey Bay Bridge	71.18
Forestry Road Culvert	71.20

According to the BCI calculation both structures are in the lower portion of the "Good" condition range.

Further to the calculated BCI values, a Summary Letter was submitted under separate cover on March 4, 2022 to the MU for the detailed inspection of the two structures in 2021. This letter also included:

- OSIM inspection reports for each structure inspected
- Inspection photographic logs
- Maintenance recommendations and summary table with estimated maintenance costs

If you have any questions, please contact the undersigned.

Regards,

STANTEC CONSULTING LTD.



Eric Tranquada B.Env.D., P.Eng.

Bridge Engineer
Phone: (204) 478-8986
Mobile: 204-228-2574
Eric.Tranquada@stantec.com

Attachment: BCI for Howey Bay Bridge
BCI for Forestry Road Culvert

Structure Name: Forestry Road Box Culvert
Structure Type: Concrete Box Culvert
Year Built: Unknown
Yr. of Last Rehab: None

Inspector: Angela Kasdorf, C.E.T.
Others in Party: Vince Friesen
Inspection Date: December 15, 2021
Type of Inspection: OSIM

Element Group	Element Description	Total Element Quantity (TEQ _i)	Unit	Unit Cost of Element (UC _i) (\$)	Total Equiv. Value (TEV _i) (\$)	Condition States				Current Element Value (CEV _i) (\$)
						Exc.	Good	Fair	Poor	
Accessories	Signs	4	Each	0	0	4	0	0	0	0.0
Barriers	Posts (Wood)	6	Each	100	600	0	0	1	5	40.0
	Posts (Steel)	17.92	Sq. m	200	3,584	17.92	0.00	0.00	0.00	3,584.0
	Railing Systems	38.00	m	200	7,600	37.80	0.00	0.00	0.20	7,560.0
Culverts	Barrel	192.96	Sq. m	350	67,536	0.00	192.60	0.00	0.36	50,557.5
	Inlet Components	3.14	Sq. m	350	1,099	0.00	2.58	0.00	0.56	677.3
	Outlet Components	3.14	Sq. m	350	1,099	0.00	2.74	0.00	0.40	719.3
	Footing	79.60	Sq. m	350	27,860	0.00	55.48	4.02	20.10	15,126.3
Coatings	Railing Systems	38.00	m	125	4,750	38.00	0.00	0.00	0.00	4,750.0
Decks	Wearing Surface	225.00	Sq. m	25	5,625	0.00	0.00	225.00	0.00	2,250.0
Embankments & Streams	Embankments	1	All	0	0	1	0	0	0	0.0
	Slope Protection	1	All	0	0	1	0	0	0	0.0
	Streams & Waterways	1	All	0	0	0	1	0	0	0.0

BCI = 71.20



Structure Name: Howey Bay Bridge

Structure Type: Steel Girder

Year Built: Unknown

Yr. of Last Rehab: 2021

Inspector:

Angela Kasdorf, C.E.T.

Others in Party:

Vince Friesen

Inspection Date:

December 14, 2021

Type of Inspection:

OSIM

Element Group	Element Description	Total Element Quantity (TEQ _i)	Unit	Unit Cost of Element (UC _i) (\$)	Total Equiv. Value (TEV _i) (\$)	Condition States				Current Element Value (CEV _i) (\$)
						Exc.	Good	Fair	Poor	
Approach	Wearing Surface	103.60	Sq. m	6	622	0.00	103.06	0.00	0.54	463.8
Abutments	Abutment Walls	19.69	Sq. m	900	17,721	0.00	14.94	0.30	4.45	10,192.5
	Ballast Walls	11.22	Sq. m	350	3,927	0.00	11.20	0.00	0.02	2,940.0
	Bearings (G1/G6)	4	Each	1,000	4,000	0	4	0	0	3,000.0
	Bearings (G2/G3/G4/G5)	8	Each	1,000	8,000	8	0	0	0	8,000.0
Accessories	Signs	5	Each	0	0	5	0	0	0	0.0
Barriers	Posts (Approach - Wood)	8	Each	100	800	0	8	0	0	600.0
	Posts (Deck - Steel)	8	Each	200	1,600	0	8	0	0	1,200.0
	Railing Systems	40.40	m	200	8,080	31.80	0.80	0.00	7.80	6,480.0
Beams/MLEs	Diaphragms	10	Each	0	0	10	0	0	0	0.0
	Girders	52.22	Sq. m	420	21,932	0.00	41.16	3.61	7.45	13,571.9
Coatings	Railing Systems	40.40	m	125	5,050	39.60	0.80	0.00	0.00	5,025.0
Decks	Wearing Surface	47.36	Sq. m	25	1,184	0.00	47.36	0.00	0.00	888.0
	Deck Top	48.64	Sq. m	120	5,837	0.00	48.64	0.00	0.00	4,377.6
	Soffit - Thin Slab (Exterior)	4.61	Sq. m	120	553	0.00	4.21	0.30	0.10	393.3
	Soffit - Thin Slab (Interior)	48.64	Sq. m	120	5,837	0.00	38.47	0.27	9.90	3,475.3
Embankments & Streams	Slope Protection	1	Each	0	0	0	0	1	0	0.0
	Streams and Waterways	1	All	0	0	0	1	0	0	0.0
	Embankments	1	Each	0	0	0	0	0	1	0.0

BCI = 71.18

